

## Preparing GerberCUT files in 10 Steps

1. GerberCut software requires vector cut lines and targets.
2. Targets and cut shapes must be assigned a CMYK color (use CMYK with values of 0 if you don't want the cut shape to print).
3. The targets should be ¼" black circles when job is printed (if the background is dark, use ¼" white circles surrounded by black).
4. Cut lines and Targets must be on their own layers.
5. Print your file to your printer, the print file must include the targets.
6. For GerberCUT, the cut files must be saved as an AI or PDF file.
7. In GerberCUT, assign I-Cut camera to the Target (or Remark) layer.
8. In GerberCUT, the target layer must be at the top of the layer tree.
9. Assign routing tool paths to the cut layer.
10. Select Target and Cut Layers and click run to send your job to the router.

